## Accessories for HydroStat Controls

## **Outdoor Sensor Kit OS-100**

Provides outdoor reset functionality.

For HydroStat Models 3200-Plus and 3250-Plus only

**48-140** Kit includes: outdoor sensor with 9' cable (additional wire to be added in field as needed), sensor mounting bracket with 2 screws and 1 wire clip, two spade connectors, knockout wire bushing.



## **Electro-Well™ Models**

To enable HydroStat's low water cut-off function.



## **Remote Mounting Options**

For all HydroStat Models except 3000 Series





Wall/Jacket Mounting Kit Kit includes: 2 mounting brackets, remote sensor, plastic grommet, rubber well cap, 4 #8x1/2" self-tapping screws.

48-101 HydroStat Wall/Jacket Mounting Kit with 2' sensor
48-102 HydroStat Wall/Jacket Mounting Kit with 4' sensor
48-103 HydroStat Wall/Jacket Mounting Kit with 10' sensor

48-104 HydroStat Wall/Jacket Mounting Kit with 20' sensor





Pipe Mounting Kit Kit includes: mounting bracket for 1" to 2" pipe, remote sensor, plastic grommet, rubber well cap.

48-121 HydroStat Pipe Mounting Kit with 4' sensor